

**FS C5016 THRU FS C5030 COLOR PRINTERS**

**METER/COUNT REPORT INSTRUCTIONS**

**SOME OF THE PANELS MAY LOOK A LITTLE DIFFERENT BUT THE INSTRUCTIONS WILL BE THE SAME.**

**PRESS THE MENU BUTTON.**

**USING THE DOWN ARROW SCROLL UNTIL YOU SEE PRINT STATUS PAGE IN THE DISPLAY**

**PRESS ENTER OR OK TWICE AND A STATUS PAGE WILL PRINT**

**UNDER PAGE INFORMATION ON THE LEFT SIDE WILL BE THE METERS**

**OPERATION PANEL**

