


KM 3035, KM 4035, KM 5035


## METER/COUNT REPORT INSTRUCTIONS

PRESS THE DEFAULT SETTING COUNTER (1) BUTTON ON THE OPERATION PANEL



IN THE DISPLAY SCREEN PRESS THE COUNTER CHECK (2) BOX

IN THE DISPLAY SCREEN PRESS THE PRINT REPORT (3) BOX



THE METER IS THE TOTAL COUNT ON THE UPPER LEFT SIDE OF THE STATUS PAGE.